Quick Guide

G.R.A.S. OP0025 Kit for Sensitivity Calibration of Surface Microphone Sets

Description

The G.R.A.S. OP0025 Kit for Sensitivity Calibration of Surface Microphone Sets contains an adapter that makes it possible to mount, secure and calibrate a G.R.A.S. surface microphone in a G.R.A.S. pistonphone.

We recommend the G.R.A.S. 42AP Intelligent Pistonphone, Class 0 because of its built-in barometer and thermometer.

Delivered Items

The following items are part of the delivery:

| Pi | istonphone Calibration Adapter for 1/4" Surface Microphone Sets | RA0202 |
|----|---|--------|
| | · | |

G.R.A.S. OP0025

Kit for Sensitivity Calibration of Surface Microphone Sets

Mounting the Microphone Set in the Adapter

If necessary, loosen the finger screw to allow the holder to turn freely.

- 1. Carefully place the microphone into the adapter. Take care not to touch the diaphragm and make sure that the microphone rests evenly in the adapter.
- 2. Turn the holder until it covers the microphone
- 3. Tighten the finger screw.

Mount the adapter in the pistonphone and calibrate according to the instructions in your pistonphone's manual. No correction factor should be applied.

